


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-284	Smoke	9/9/2009	ADS/TM	S11KK1019MH	Dry	Yes	906.81



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-284	Smoke	9/9/2009	ADS/TM	S11KK1019MH	Dry	Yes	906.81

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11KK1018G1	S11KK1018MH	S11KK1010MH	82.3449	8
S11KK1015G1	S11KK1015MH	S11KK1019MH	178.235	8
S11KK1019G1	S11KK1019MH	S11II1047MH	162.45	8
S11II1004G1	S11II1004MH	S11II1030MH	213.802	8
S11KK1010G1	S11KK1010MH	S11KK1015MH	37.4716	8
S11II1047G1	S11II1047MH	S11II1004MH	232.505	8

Observations & Photos

Obs_ID S1028-284-OB01

Address 4601 Homer Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1010MH

Comments Smoke from cleanout in front yard. 4601 Homer Ave.



Picture \S1028-284-OB01-P01.jpg

Comments Front of house, 4601 Homer Ave.

Obs_ID S1028-284-OB02

Address 4603 Homer Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1010MH

Comments Smoke from cleanout in front yard. 4603 Homer Ave.



Picture \S1028-284-OB02-P01.jpg

Comments Front of house, 4603 Homer Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-284	Smoke	9/9/2009	ADS/TM	S11KK1019MH	Dry	Yes	906.81

Obs_ID S1028-284-OB03

Address 4605 Homer Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1010MH

Comments Smoke from cleanout in front yard. 4605 Homer Ave.



Picture \S1028-284-OB03-P01.jpg

Comments Front of house, 4605 Homer Ave.

Obs_ID S1028-284-OB05

Address 3303 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1015MH

Comments Smoke from cleanout in front yard. 3303 Royce Ave.



Picture \S1028-284-OB05-P01.jpg

Comments Front of house, 3303 Royce Ave.

Obs_ID S1028-284-OB04

Address 4611 Homer Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1018MH

Comments Smoke from cleanout in front yard. 4611 Homer Ave.



Picture \S1028-284-OB04-P01.jpg

Comments Front of house, 4611 Homer Ave.

Obs_ID S1028-284-OB06

Address 3313 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1019MH

Comments Smoke from cleanout in front yard. 3313 Royce Ave.



Picture \S1028-284-OB06-P01.jpg

Comments Front of house, 3313 Royce Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-284	Smoke	9/9/2009	ADS/TM	S11KK1019MH	Dry	Yes	906.81

Obs_ID S1028-284-OB07

Address 3425 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11II1047MH

Comments Smoke from cleanout in front yard. 3425 Royce Ave.



Picture \S1028-284-OB07-P01.jpg

Comments Front of house, 3425 Royce Ave.

Obs_ID S1028-284-OB09

Address 3410 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11II1047MH

Comments Smoke from cleanout in front yard. 3410 Royce Ave.



Picture \S1028-284-OB09-P01.jpg

Comments Front of house, 3410 Royce Ave.

Obs_ID S1028-284-OB08

Address 3412 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11II1047MH

Comments Smoke from cleanout in front yard. 3412 Royce Ave.



Picture \S1028-284-OB08-P01.jpg

Comments Front of house, 3412 Royce Ave.

Obs_ID S1028-284-OB10

Address 3402 Royce Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11KK1019MH

Comments Smoke from cleanout in front yard. 3402 Royce Ave.



Picture \S1028-284-OB10-P01.jpg

Comments Front of house, 3402 Royce Ave.